

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
Company	Vicky Miller
OGM	Steve Demczak

Inspection Report

Permit Number:	C0070018				
Inspection Type:	PARTIAL				
Inspection Date:	Wednesday, June 15, 2011				
Start Date/Time:	6/15/2011 2:00:00 PM				
End Date/Time:	6/15/2011 3:00:00 PM				
Last Inspection:	Thursday, May 19, 2011				

Inspector: Steve Demczak, Weather: Sunny Upper 70's

InspectionID Report Number: 2779

Types of Operations

Reprocessing

Accepted by: jhelfric 7/11/2011

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY Site: SOLDIER CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,624.64	Total Permitted			
24.32	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

Other

✓ Federal ✓ Underground State Surface County Loadout Processing Fee

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition: Canyon Fuel Company has just one permit condition for the Soldier Canyon Mine; to submit water quality data in an electronic format through the Electronic Data Input web site.

Permitting Actions: None

Inspector's Signature:

Steve Demczak,

Date

Thursday, Jur



Permit Number: C0070018
Inspection Type: PARTIAL

Inspection Date: Wednesday, June 15, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	V		~	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.1	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070018 Inspection Type: PARTIAL

Inspection Date: Wednesday, June 15, 2011

Page 3 of 3

2. Signs and Markers

The identification sign was on the side of the main road overlooking the sediment pond. The information addressed the requirements of the R645 Coal Rules. Carbon County Road Department installed a small vertical signs on a small post showing road construction throughout the canyon. It is located next to the parking lot guardrail in the permit area but outside the disturb area. Since, this is a non-related to coal mine. There is no problem with this action.

3. Topsoil

The topsoil piles are located below the mine. There were no signs of wind or water erosion.